

Tar epoxy resin paint Hydrotar 134

Tar epoxy resin paint Hydrotar 134 is two component type paint based on waterborn Tar epoxy resin.

epoxy resin.

CHARACTERISTICS

- It is recommended as a water-based paint for concrete..
- 100 microns can be applied in one painting.
- Being a waterborn agent, it is a environment-friendly product to take the worker's safety into account.
- It has excellent resistance to acid, alkali, salt and water.

RECOMMENDED USE

- Wastewater treatment for sewage, wastewater Concrete tank bottom and wall protection.
- Concrete storage tank interior
- Inside the storage tank of wastewater treatment facility
- Maritime structures in a highly corrosive environment
- Protecting structures buried underground

PHYSICAL PROPERTIES

Colors Black.
Volume Solids 60%
Recommended Dry Film Thickness

(maximum thickness 200 \mum) 100 \mum

- Theoretical Coverage 6.4m2 /liter (100 \(m\))

 (0.21kg/m^2)

- High Gloss
- * The discoloration may be occurred under long term exposure of sunlight.
- * Discoloration and loss of gloss is observed when it is continued in high temperature

- Chemical Resistance

Exposure	Condensation	fumes
acids	Good	Good
alkalis	Excellent	Excellent
solvents	Good	Excellent
water	Excellent	Excellent
salt	Excellent	Excellent

- Not Recommended for:
- * Immersion and exposure to strong acids and solvents.
- * Exposure to direct sun light for a long time.

It may cause the losing of gloss, discolor and eventually chalk.

- * It is affected by the temperature exposed during deposition and is not recommended above 50 °C
- Compatibility
 - * Compatible with most aqueous epoxies However,

please consult with us in advance.

THINNER

- Not Required
- If use something water 10%.

MIXING RATIO

-A : B = 4 : 1 (by weight)

PACKING UNIT

- Main Agent (part A): 16kg Hardener (part B): 4kg

STORAGE CONDITIONS

- Store it indoors.
- Temperature: 4~43 °C
- Relative Humidity: 0~90% (sealed condition)
- The remained paint should be sealed after use

SHELF LIFE

- 12 months (at room temperature)

PRECAUTIONS

- Sufficient ventilation and protective gloves, masks and protective gear to wear.
- Keep away from open flames.
- After using leftover paint in direct sunlight to reach the seal must be a cool place.
- Keep out of reach of children to save.
- Absolute intake can cause health disorders or steam inhalation, skin contact, or are not careful.
- In case of ingestion or skin contact, administrate first aid according to notice on container or Material Safety Data Sheet(MSDS), and see the doctor immediately.
- Do not use other purpose except original recommended use.
- * This document is exact, but it can be changed for quality improvement without notice. For more detailed information, contact to Technical Center of ur company.



Tar epoxy resin paint Hydrotar 134

SCOPE

This Direction for use applies to **Tar epoxy resin** paint Hydrotar 134.

This is a standard guide. If there are anything different from the specification at the workplace, please follow the specification.

WORKING CONDITION

- Painting Tools: power mixer, brush, roller, air spray, masking tapes and so on.
- Pot Life: 5 hour. (25°C)
- Dry through: $6\sim7$ hours $(25^{\circ}\text{C})/100~\mu\text{m}$ It should be dried for at least 5 days (25°C) when immersed.

- Time to recoat: 1~2 days (25°C)

	, ,	/
Surface temperature	Time to recoat	Dry through
10°C	40 hours	10 days
15°C	30 hours	8 days
25°C	16 hours	7 day
32°C	12 hours	5 day

- Application Conditions

	Material(°C)	Surface	Ambient	Humidity(%)
min	5	5	5	0
nor	20~25	20~25	20~25	Below 80
max	32	32	35	Up to 85

- * These can be different under the working environments.
- * Do not apply unless surface is 3°C above the dew point.

SURFACE TREATMENT

- Employ adequate methods to remove dirt, dust, oil and all other contaminants that could interfere with adhesion of the coating.
- Previously painted surfaces should be scraped clean of flaky or peeling paint.
- Needed the proper preparation and recommended a primer.
- The cure time of concrete.

Temperature (°C)	Drying times (days)	
24	More than 28	
21	30~	
10	40~	
7	60~	

- Remove any oil or grease from surface to be coated with clean rags soaked in JeongSeok Thinner #001, #003 or toluol in accordance with

SSPC-SP-1.

DIRECTIONS FOR WORK

- 1. Priming
- Surfaces must be clean and dry.
- Porous concrete may require a primer to achieve a satisfactory surface for painting.
- This will improve hydrophobic surface properties.
- 2. Application Tar epoxy resin paint Hydrotar 134.
 - The optimum time to topcoat is when the primer is "touch-tacky".
- Keep the interval of repainting described and make the thickness of its dried paint film over 1mm.
- Use moderate rake and trowel.
- If those maximum recoat times have been exceeded, the surface must be abraded by sweep blasting or sanding prior to the application of additional coats.

PRECAUTIONS

- Avoid painting in a rainy or humid day (over 85%) and under less than 5°C as it can make poor paint film (Cracks or bad adhesion in the coating layers).
- MSDS is recommended for more information.
- Do not use it under the direct rays of sun in summer.
- Personnel protective clothing should include goggles, rubber gloves, and full length clothing.
- In case of skin contact, remove contaminated clothing and wash affected area thoroughly with soap and water for a minimum of 15 minutes. Then contact a physician.
- Please treat it with the paint 28 days after the cement mortar got the final treatment and it is below ph 9 and 8% moisture content.
- Keep adequate ventilation during the application.
- Keep it away from ignition.
- Make sure that the paint should not be kept for a long time after opening and the remaining paint should be sealed after use.
- Do not apply when air or surface temperature is below 10°C or when rain or high humidity is imminent.
- * This document is exact, but it can be changed for quality improvement without notice. For more information, contact to Technical Center of our company.